

This photo was taken
before the rebuilding of
the vestibule & the porch.
Therefore the new tread
is not shown.

Stone wall is Front Lot Line

Area of Proposed ramp

